

## DYNAPAC CP224

### Description

Dynapac CP224, Cummins , QSB3.3, 74kW, EPA, 14/70-20, Erops cabin, Water sprinkler system, Moveable seat, Speed meter, Air conditioning, Backup camera, Backup alarm, Beacon, In very good and very clean condition.



<b>Year</b>	2010
<b>Hours</b>	4575
<b>Weight</b>	9.600 kg
<b>Serial number</b>	10000501JOB000727
<b>Reference</b>	197635



[Download photos](#)

**CONTACT US:**  
**SALES@SMITMA.COM**  
**+31(0)773999840**

New/Excellent ★★★★★	Very good ★★★★☆	Good ★★★☆☆	Fair ★★★☆☆	Poor ★☆☆☆☆
------------------------	--------------------	---------------	---------------	---------------



# INSPECTION REPORT

---

## FEATURES

Engine brand	Cummins
Engine model	QSB3.3
Engine power in kW	74kW
EPA	✓

## DOCUMENTS

Parts book	✓
Operation manual	✓

## GENERAL APPEARANCE

Serial number plate checked	Yes
Paint	★★★★
Decals	★★★★
Bonnet	★★★★
Chassis	★★★★
Cabin	★★★★

## ENGINE DETAILS AND CONDITION

Engine number	68314354
EPA sticker available	Yes
Air cleaner	New
Anti-freeze level °C	-30°C
Diesel anti-freeze added	Yes
Diesel level ok	Yes
Cooling liquid level ok	Yes
Engine oil level ok	Yes
Exhaust manifold	★★★★
Muffler	★★★★
Exhaust stack	★★★★
Hoses	★★★★
Good cold start	Yes
Engine power	★★★★
Blow by	★★★★
Knocking	No
Compression in the radiator	No

Water in the oil	No
Oil in the water	No
Smoke	Normal
Engine leaks	No
Belts and pulleys	★★★★☆
Fan	★★★★☆
Radiator	★★★★☆

## SAFETY ITEMS

Backup alarm	Working
Backup camera	Not working
Seat belt	Available
Horn	Working
Parking brake	Working
Beacon	Working

## OPERATOR STATION

Hourmeter	Working
Air conditioning	Not Working
Heater	Working
Gauges	Working
Switches	★★★★☆
Display	★★★★☆
Warnings	No Warnings Available
Mirrors	Small crack, no need to repair
Cabin glass	Not broken
Windshield wipers	Working
Interior lights	Working
Cabin floor	★★★★☆
Interior roof	★★★★☆
Seat	★★★★☆
Door lock	Working

## STEERING

Steering cylinders leaking	No
Play steering cylinders	★★★★☆

## HYDRAULICS

Hydraulic level ok	Yes
--------------------	-----

Hydraulic lines and fittings	★★★★★
Hydraulic tank/sight glass and cap	★★★★★
Noise hydraulic pump normal	Yes
Operation condition hydraulics	★★★★★

### ELECTRICAL, STARTING AND CHARGING SYSTEM

Alternator functioning	Yes
Wiring	★★★★★
Batteries	★★★★★
Starter	★★★★★
Cabin lights working	Yes
Tail lights	Yes

### FRONT TYRES

<b>FIRST TYRE</b>	
Percentage life remaining	50%
<b>SECOND TYRE</b>	
Percentage life remaining	60%
<b>THIRD TYRE</b>	
Percentage life remaining	60%

### REAR TYRES

<b>FIRST TYRE</b>	
Percentage life remaining	70%
<b>SECOND TYRE</b>	
Percentage life remaining	60%
<b>THIRD TYRE</b>	
Percentage life remaining	70%
<b>FOURTH TYRE</b>	
Percentage life remaining	60%

New/Excellent ★★★★★	Very good ★★★★★	Good ★★★★★	Fair ★★★★★	Poor ★★★★★
------------------------	--------------------	---------------	---------------	---------------

